

September 27, 2019

CERTIFIED MAIL: 7018 0680 0000 1036 1823

RETURN RECEIPT REQUESTED

Chief, Environmental Enforcement Section Environment and Natural Resources Division U.S. Department of Justice Box 7611 Ben Franklin Station Washington, D.C. 20044-7611

Re: DOJ No. 90-5-2-1-10459

CERTIFIED MAIL: 7018 0680 0000 1036 1809

RETURN RECEIPT REQUESTED
Director, Air Enforcement Division
Office of Civil Enforcement
U.S. EPA Headquarters, MC 2242A
1200 Pennsylvania Ave., NW
Washington, D.C. 20460

CERTIFIED MAIL: 7018 0680 0000 1036 1816

RETURN RECEIPT REQUESTED

Chief, Air and TRI Section Enforcement Division U.S. Environmental Protection Agency Region 9 75 Hawthorne Street San Francisco, CA 94105

RE: Consent Decree No. CV-15-02206-PHX-DLR – Notification of Operating Limit Exceedance

To whom it may concern:

ASARCO LLC (Asarco) is submitting this notification per Consent Decree No. CV-15-02206-PHX-DLR Paragraph 57 of an emission limit exceedance. Between September 26, 2019 at 17:00 and September 27, 2019 at 10:00 the rolling eight (8) hour emission limit of 23 mg/dscm was exceeded at the Flash Furnace Vent Gas Baghouse as specified in Paragraph 19.a. After performing maintenance in the Flash Furnace Vent Baghouse, a maintenance crew shut a door to one of the modules which induced a draft. This draft picked up particles of rust from the baghouse floor and walls and

Consent Decree No. CV-15-02206-PHX-DLR Notification of Operating Limit Exceedance September 27, 2019 Page 2

introduced the particles to the air stream. The door was closed at approximately 12:45pm on 9/26/19 but the emission limit was not exceeded until 17:00 on 9/26/19 with a value of 25.23 mg/dscm. The emission limit was exceeded for each subsequent hour until 9:00am on 9/27/19 when the door was opened to the module. After opening the door, the instantaneous readings fell below the emission limit, however the eight-hour rolling average did not go below the limit until 9:00am on 9/27/19. Maintenance crews have been instructed not to close doors between modules as that action can introduce excess particles into the airstream.

If there are any questions, please contact Jeff Anderson at (520) 356-3208.

Steve Gasser Smelter Manager Hayden Operations

SG/rcg

pc: I

R. Rubio

A. Veek